



.tran 10m

For 35V Supply R16,R18= 10K
 For 42V Supply R16,R18= 22K
 For 60V Supply R16,R18= 30K